



## SF-RAZ – характеристики



**Fig. 4**  
3 self centering jaws center and clamp the coupling.



**Fig. 5**  
When the coupling is centered and clamped ,3 compensating jaws clamp the coupling additionaly to distribute the total clamping force onto 6 jaws = less deformation of the coupling/perfect roundness of thread.